


# AIR POLE ASSEMBLY



## PARTS LIST

NO.	PART NO.	DESCRIPTION	QTY.
1	104-TB	3/4" TOP BUSHING	1
2	120-OR	O-RING SEAL	1
3	108-GB-SQ	GUIDE BUSHING	1
4	125-SS	1/4-20 x 5/16 SETSCREW	9*
4A	128-SS	3/8-16 x 3/8 HELICOIL	9*
5	EP-171-58	58" OUTSIDE POLE	1
6	EP-100-42-AO	42" INSIDE POLE	1
7	126-NS	NYLON SLEEVE	2
8	497-SC	STOP COLLAR	2
9	112-SM2	2" OFFSET SIDE MOUNT	2
10	120-KB	HAND KNOB	1
11	120-ST	HAND KNOB STUD	1
11A	127-SS	3/8-16 x 3/8 THR. COIL	1
12	358-RS	8-32 x 1/4" SCREW	2
13	487-OR	AIR PISTON O-RING**	2
14	450-NR	1.375" AIR PISTON**	1
15	451-VR	AIR PISTON V-RING**	1
16	132-SR	3/8" STRAIN RELIEF	1
17	480-CC	16/3 COIL CORD, 6 FT.	1
18	106-AB	BOTTOM BUSHING	1
19	418-SR	1/2" STRAIN RELIEF	1
20	466-TF	1/4" AIR-IN COUPLING	1
21	124-SS	1/4-20 x 1/4 SETSCREW	4

### NOTES:

\*THREE EACH FOR PARTS 3 & 8.

\*\*PART IS COATED WITH SILICON LUBRICANT.

## OPTIONAL PARTS LIST

NO.	PART NO.	DESCRIPTION	QTY.
22	201-MG	UP SWITCH MAGNET	1
23	200-SW	UP INDICATOR SWITCH	1
24	203-BS	4-40 x 1/2" SCREW	2

ISO-9001 CERTIFIED



**Akron Brass Company**  
A Premier Farnell Company

501 N. Cummings Lane, Washington, IL 61571  
Phone: (309)444-4440 Fax: (309)444-8766